INSPECTION REPORT

PERMIT	NUMBER:	BP-15-00209	OWNER'S NAME:	FEASIER	
DATE:		9/16/2015	TYPE:	Exterior shear	
TIME STARTED:		2:26 PM	INSPECTOR:	Jeremy Haberman	
MAP NUMBER:		20-14-24050-0002			
1	1. All Shearwall Holdowns Must Connect to (2) Full Height Studs. Holdown Connected to Only				
	One Full Height Stud Next to Window.				
2	2. Communications Panel Installation Severed Panel Edge Stud. 2' x 3' Sheeting Removed in				
S	Shearwall Panel.				
3	3. Bathroom in Garage Not Permitted. Revision Required. Slab Insulation Required Under Bat				
h	hroom.				
4	4. NOTE: Photos of Panel Compromise in 'T Drive.				
INSTRUCTIONS: Submit for Revision. Make Corrections Above. DO NOT COVER EXTERIOR.					
NEXT INSPECTION: Reinspect					
RE-INSPECTION FEE DUE? VES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	ieremv.haberman @co.kittitas.wa.us				
 INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 ◆ 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 ◆ Main Office Line: 509-962-7506 					