INSPECTION REPORT

PERMIT NUMBER:	BP-15-00220	OWNER'S NAME:	MCCONNELL
DATE:	5/20/2016	TYPE:	Exterior shear
TIME STARTED:	2:03 PM	INSPECTOR:	Justin Bennett
MAP NUMBER:	17-19-33030-0012		
 Engineer letter on site for STD straps for stub walls Provide engineer approval for first floor misalignment with stub wall @ back of house (2) locations Supply @ 90#/15 mins - Ok DWV on Stack - Ok Plumbing rough in Ok Gas @ 70#/15 mins - Ok 			
INSTRUCTIONS: Provide engineer approval for First Floor NEXT INSPECTION: Mechanical			
DE INCRECTION SEE	DUES NO VEC		ć
RE-INSPECTION FEE		PAID PRIOR TO SCUE	\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			
ADDRESS:iustin.bennett @co.kittitas.wa.us			

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506