



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-15-00220

OWNER'S NAME: MCCONNELL

DATE: 2/10/2017

TYPE: Mechanical

TIME STARTED: 10:10 AM

INSPECTOR: Jeremy Haberman

MAP NUMBER: 17-19-33030-0012

1. Corrections OK.
 2. Mechanical Rough In OK.
 3. Mechanical Exhaust OK.
 4. Fireplace Rough IN OK.
 5. Draftstop Required in Fireplace Chase.
 6. Verify Duct Insulation In Crawl and Garage at Insulation Inspection.
 7. Truss Sheets Not Provided. TRUSS VERIFICATION REQUIRED.
 8. Header at Master Bedroom Not Per Plan.
 9. 2x12 Rafter to Beam Connection Over Stairs Connection Not Acceptable. Provide Connection Detail to Plan Review. **OK to use Simpson LRU26Z hangers. MF 2/10/17**
 10. Full Bearing Required Under 8" Wide Beam in MAster Bedroom Lid.
- Full underfloor fire protection or sprinkler system required where crawlspace is 5'-0" height.**

INSTRUCTIONS: OK to Insulate. Will See Corrections at Insulation.

NEXT INSPECTION: Insulation.

RE-INSPECTION FEE DUE? ☒ NO ☐ YES \$ _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL
ADDRESS: jeremy.haberman @co.kittitas.wa.us

INSPECTION REQUEST LINE: 509-962-7694

<http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx>

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506