



KITITITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

## INSPECTION REPORT

PERMIT NUMBER: BP-15-00263

OWNER'S NAME: DUNCAN

DATE: 2/23/2016

TYPE: Frame-Plumb-Mech

TIME STARTED: 11:41 AM

INSPECTOR: Jessica Contratto

MAP NUMBER: 17-17-01052-0003

1. DWV at 5#, H20 at, 50# -ok
2. Gas at 15#-ok
3. Truss bracing missing on A01, B01, C01, E01, F01. Circled on truss sheets
4. Strap top of girder truss in entry to adjacent top plate
5. Clip ends of above girder truss to supporting wall (H2.5)
6. Interior BWP not nailed per requirements on garage separation walls. Circled on plans. 6 and 12 pattern
7. Woodstove chimney requires protection to combustibles in attic
8. Laundry room must have fire rated door assembly or all penetrations in wall must be fire rated
9. Washer box must be fire protected or rated. 5/8" drywall box can be built around it. Dryer vent must be 26Ga metal
10. Maintain slope on plumbing vents
11. Exhaust ok
12. Wall heaters used

INSTRUCTIONS: Complete above, ok to insulate

NEXT INSPECTION: insulation/corrections

RE-INSPECTION FEE DUE?  NO  YES \$ \_\_\_\_\_

**IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION**

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL  
ADDRESS: \_\_\_\_\_ [jessica.contratto @co.kittitas.wa.us](mailto:jessica.contratto@co.kittitas.wa.us)

**INSPECTION REQUEST LINE: 509-962-7694**

<http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx>

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506