INSPECTION REPORT

PERMIT NUMBER:	BP-15-00281	OWNER'S NAME:	MCDANIEL
DATE:	4/11/2016	TYPE:	Floor framing
TIME STARTED:	11:20 AM	INSPECTOR:	Justin Bennett
MAP NUMBER:	20-14-12051-0506		
Provide through pony wall access to each bay			
INSTRUCTIONS: Complete underfloor access/Once complete Ok to cover/Verify access @ next inspection			
	•		
NEXT INSPECTION:	Exterior Shear		
RE-INSPECTION FEE DUE? VES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			
	ADDRESS:	NSPECTOR AT THE FO <u>iustin.bennett</u> @	
INSPECTION REQUEST LINE: 509-962-7694			
http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx			
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			