INSPECTION REPORT

PERMIT NUMBER:		BP-15-00282	OWNER'S NAME:	BOITANO	
DATE:		7/7/2015	TYPE:	Exterior shear	
TIME STARTED:		9:59 AM	INSPECTOR:	Jeremy Haberman	
MAP NUMBER:		18-18-26051-0007			
	1. Holdowns	Missing at ABWP on Exterior. (4)) 1800# Hold Down	s Required. See "Orange" Marki	
	ngs on Floor Plan and Inspector JBs Note on Foundation Plan Date 6/17/15				
	2. Trusses OK.				
	3. Additional Window in Den Not Per Plan.				
	4. Window Headers Not Per Plan.				
	5. Crawl Access Required.				
	6. Plumbing/Mechanical/Electrical Inspections Not Complete.				
INSTRUCTIONS: Make Corrections Above. Call For Re Inspection. Inspector Can Be Reached at					
NEXT INSPECTION: Framing					
RE-INSPECTION FEE DUE? VES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	jeremy.haberman @co.kittitas.wa.us				
• INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 • 411 N. Ruby Street, Suite 2. Ellensburg, WA 98926 • Main Office Line: 509-962-7506					