INSPECTION REPORT

PERMIT NUMBER: BP-15-00292 OWNER'S NAME: STRADER

DATE:	7/30/2015	TYPE:	Floor framing
TIME STARTED:	11:57 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-15-19050-0145		
1. floor fra	ming ok		
2. Note- 3x sill plate used on entire house-ok			
INSTRUCTIONS: (ok to cover		
NEXT INSPECTION: shearwalls			
RE-INSPECTION FE	E DUE? NO	YES	\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
iessica.contratto @co.kittitas.wa.us			
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			