INSPECTION REPORT

INSPECTION REPORT			
PERMIT NUMBER:	BP-15-00299	OWNER'S NAME:	PERAVOZ
DATE:	3/2/2016	TYPE:	Shearwalls
TIME STARTED:	12:04 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	21-14-34060-0003		
1. Blocking in floor framing completed 2. Exterior nailing and straps ok 3. Engineer clarification needed for CS straps over header at garage gable windows. No headers needed? 4. Finish install of interior holddowns and shearwalls 5. Stitch nail multiple 2x members at hold downs INSTRUCTIONS: Ok to cover exterior			
NEXT INSPECTION: Plumb/mech			
RE-INSPECTION FEE			\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			

INSPECTION REQUEST LINE: 509-962-7694

ADDRESS:__

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506

iessica.contratto @co.kittitas.wa.us