INSPECTION REPORT

PERMIT NUMBER:		BP-15-00329	OWNER'S NAME:	LYNCH	
DATE:		7/22/2015	TYPE:	Exterior shear	
TIME STARTED:		3:56 PM	INSPECTOR:	Justin Bennett	
MAP NUMBER:		20-17-15040-0002			
	4 = 4 : 0				
	1. Exterior Shear Ok				
	2. HD installation Ok				
	3. Floor to floor straps Ok				
	4. Ok to cover exterior				
	5. Framing Ok				
	6. Attic reinforcement Ok				
	7. Ok to insulate				
INSTRUCTIONS: Ok to cover exterior/Ok to insulate					
NEXT INSPECTION: Insulation					
RE-INSPECTION FEE DUE? NO YES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	iustin.bennett @co.kittitas.wa.us				
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 •					
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506					