INSPECTION REPORT

TYPE:

OWNER'S NAME: CASCADE VIEW INC

Slab plumbing

BP-15-00366

6/29/2015

PERMIT NUMBER:

DATE:

TIME STARTED:		9:32 AM	INSPECTOR:	Justin Bennett
MAP NUMBER: 18		18-17-36057-0004		
	1. Plumbing	not complete		
	2. Exterior Piers not complete			
	3. Slab Insulation Ok			
	4. Do Not Backfill			
INSTRUCTIONS: Do not backfill/Plumbing not complete/Re-Inspection				
NEXT INSPECTION: Re-Inspection				
RE-INSPECTION FEE DUE? VES \$				
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION				
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:				
iustin.bennett @co.kittitas.wa.us				
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 				