



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-15-00379

OWNER'S NAME: YUCKERT

DATE: 7/7/2016

TYPE: Framing

TIME STARTED: 10:48 AM

INSPECTOR: Jeremy Haberman

MAP NUMBER: 17-16-14040-0002

1. Plumbing CCorrections OK.
2. DWV on Stack OK. Supply at 100#/15min. OK.
3. Truss Bracing Missing On B02 Trusses. Circled On Truss Sheet By Inspector.
4. Break in Top Plate over Master Bedroom Window Closer than 2 Feet.

INSTRUCTIONS: MAke Corrections Above. OK to Insulate.

NEXT INSPECTION: Insulation.

RE-INSPECTION FEE DUE? ☒ NO ☐ YES \$ _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL
ADDRESS: jeremy.haberman @co.kittitas.wa.us

INSPECTION REQUEST LINE: 509-962-7694

<http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx>

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506