INSPECTION REPORT

INSPECTION REPORT			
PERMIT NUMBER:	BP-15-00396	OWNER'S NAME:	EVANS
DATE:	2/26/2016	TYPE:	Frame-Plumb-Mech
TIME STARTED:	3:06 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	19-16-08020-0018		
1. H1 clips at 48" on back porch trusses and upper open deck addition 2. Lateral load connection at 2 places on back deck per S1/D10 3. Attach LSL rim to attic truss per detail 1 on S11 4. DWV on stack-ok 5. Engineer ok needed for existing garage door header cut out for inset of new beam. Clarify if any strapping or hardwate needed 6. Retro hold downs ok 7. All other framing ok 8. Truss bracing ok INSTRUCTIONS: Complete above, ok to insulate			
NEXT INSPECTION:			
Insulation/corrections			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: iessica.contratto @co.kittitas.wa.us			
	, , , , , , , , , , , , , , , , , , ,	<u> </u>	

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506