## **INSPECTION REPORT**

PERMIT NUMBER:		BP-15-00409	OWNER'S NAME:	OWENS/VOSHALL	
DATE:		8/6/2015	TYPE:	Insulation	
TIME STARTED:		2:13 PM	INSPECTOR:	Jessica Contratto	
MAP NUMBER:		18-18-22054-0004			
	1. H2O at 98	3#_ok			
	2. bedroom windows do not meet egress. Max height to sill is 44". Platform must be perman				
	ently installed for each egress window or window lowered				
	Range vent cannot down size from hood outlet. Installation of UL listed ductless is opt				
	ion				
	4. Floor joists ledgered on rim board on exterior wall. Not per plan.				
	5. see knee braces at final				
	6. see fresh air at final				
		7. see wall heaters at final			
	8. insuation ok. Use PVA primer in lieu of vapor barrier				
	C. Inicadion on Coc 1 V/ Cprimor in lied of Vapor barrior				
INSTRUCTIONS: obtain fix or approval for ledger. Approval for cover after receipt					
INSTRUCTIONS: obtain fix or approval for ledger. Approval for cover after receipt					
NEXT INSPECTION: final. Do not cover until approved					
RE-INSPECTION FEE DUE? VES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	iessica.contratto @co.kittitas.wa.us				
• INSPECTION REQUEST LINE: <a href="www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506					