INSPECTION REPORT

| INDI ECHOR KEI OKI | | | |
|--|------------------|---------------|-------------------|
| PERMIT NUMBER: | BP-15-00420 | OWNER'S NAME: | LINDENFELSER |
| DATE: | 5/18/2016 | TYPE: | Exterior shear |
| TIME STARTED: | 10:52 AM | INSPECTOR: | Jessica Contratto |
| MAP NUMBER: | 19-14-03020-0021 | | |
| 1. Exterior shear ok | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| INSTRUCTIONS: Ok to cover | | | |
| | | | |
| NEXT INSPECTION: | Frame/plumb/mech | | |
| RE-INSPECTION FEE | DUE? V NO YES | | \$ |
| IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION | | | |
| QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL | | | |
| ADDRESS: <u>iessica.contratto</u> @co.kittitas.wa.us | | | |

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506