INSPECTION REPORT

PERMIT NUMBER: BP-15-00636 OWNER'S NAME: CARTER

DATE:	10/29/2015	TYPE:	Floor framing
TIME STARTED:	2:47 PM	INSPECTOR:	Jeremy Haberman
MAP NUMBER:	17-20-29054-0004		
1. Floor Framing OK.			
INSTRUCTIONS: OK to Sheet Floor			
memberiene: Office fricor			
NEXT INSPECTION: Shear			
RE-INSPECTION FEE DUE? VES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
ieremv.haberman @co.kittitas.wa.us			
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 			