INSPECTION REPORT

PERMIT NUMBER:	BP-15-00706	OWNER'S NAME:	DAKOTA HEIGHTS
DATE:	5/10/2016	TYPE:	Footings
TIME STARTED:	12:09 PM	INSPECTOR:	Jeremy Haberman
MAP NUMBER:	19-16-06052-0009		
 Setbacks OK. Footings OK. Interior and Exterior Footings Not Inspected. Will likely be Poured with Wall s. SEVERAL SPREAD FOOTINGS MISSING. Bubbled on Plan in Blue Ink. 			
INSTRUCTIONS: Provide Photos of Spread Footings to Inspectors Email Prior to Pour.			
NEXT INSPECTION:	Walls.		
RE-INSPECTION FEE DUE? V NO YES \$ IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: <u>ieremv.haberman</u> @co.kittitas.wa.us			
INSPECTION REQUEST LINE: 509-962-7694 http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			
, , , = === = = = = = = = = = = = = = =			