



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-15-00761

OWNER'S NAME: CATLIN

DATE: 2/19/2016

TYPE: Exterior shear

TIME STARTED: 9:07 AM

INSPECTOR: Jeremy Haberman

MAP NUMBER: 17-19-06090-0007

1. Full Set of Drawings Not Onsite. Page 6 Needed for Shearwall Details.
2. Portal Frame Walls Not Per Prescriptive PFW Detail. Verify Page 6 at Reinspection.
3. ABW Panels Straps Not Nailed.
4. Sill Plates Missing Plate Washers Throughout. Verify Spacing.
5. NOTE: ROOF NAILING INSPECTION NOT REQUIRED. OK TO INSTALL ROOF PRODUCT.

INSTRUCTIONS: Make Corrections Above.

NEXT INSPECTION: Shear Reinspect.

RE-INSPECTION FEE DUE?



NO



YES

\$ _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL
ADDRESS: jeremy.haberman @co.kittitas.wa.us

INSPECTION REQUEST LINE: 509-962-7694

<http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx>

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506