INSPECTION REPORT

INSPECTION REPORT			
PERMIT NUMBER:	BP-15-00783	OWNER'S NAME:	MUNDY
DATE:	7/25/2016	TYPE:	Rough-in plumbing
TIME STARTED:	11:45 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	17-19-28000-0018		
 DWV at 6#-ok H20 at 65#-ok Detail 2/S5.4 not complete. Lateral bracing per truss manufacturer ok Steel framing ok Special inspection records on site Roof nailing was inspected by special inspector. Have report onsite for verification 			
INSTRUCTIONS: Complete above, call for re-inspection			
NEXT INSPECTION:	Re-inspect		
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			
	ADDRESS:je	essica.contratto @	co.kittitas.wa.us

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506