INSPECTION REPORT

PERMIT NUMBER:	BP-15-00798	OWNER'S NAME:	ZIEGLER
DATE:	6/20/2016	TYPE:	Framing
TIME STARTED:	9:38 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-15-29051-0094		
on 2. Gas at 30#-ok 3. Trusses ok 4. Framing ok	top downdraft vent duct where co	ollapsed inside at f	loor penetrati
INSTRUCTIONS: Ok to insulate			
NEXT INSPECTION:	Insulation/hydronics		
RE-INSPECTION FEE DUE? IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			
ADDRESS: <u>iessica.contratto</u> @co.kittitas.wa.us			
INSPECTION REQUEST LINE: 509-962-7694			

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506