## **INSPECTION REPORT**

PERMIT NUMBER:	BP-15-00874	OWNER'S NAME:	COOPER
DATE:	6/26/2017	TYPE:	Mechanical and plumbir
TIME STARTED:	10:23 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	18-19-35050-0007		
<ol> <li>DWV not on test. Cap blew off.</li> <li>H20 is live-ok</li> <li>Gas at 17#/15-ok</li> <li>Trusses ok</li> <li>Framing ok</li> <li>Range vent not in yet. Will be installed by final- downdraft</li> </ol>			
INSTRUCTIONS: O	k to insulate, see DWV then		
NEXT INSPECTION: Insulation			
RE-INSPECTION FEE			\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL  ADDRESS: <u>iessica.contratto</u> @co.kittitas.wa.us			
INCRECTION REQUEST LINE, FOR ACC 7504			

**INSPECTION REQUEST LINE: 509-962-7694** 

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506