## **INSPECTION REPORT**

|  |             |        | J             |                   |
|--|-------------|--------|---------------|-------------------|
| PERMIT NUMBER:   | BP-15-0088  | 2      | OWNER'S NAME: | HORNBACK          |
| DATE:  | 10/4/2016   |        | TYPE:         | Exterior shear    |
| TIME STARTED:  | 4:11 PM     |        | INSPECTOR:    | Jessica Contratto |
| MAP NUMBER:  | 21-12-22000 | 0-0012 |               |                   |
| Shear nailing Also inspected Framing ok  |             |        |               |                   |
| INSTRUCTIONS: Ok to cover exterior and insulate if desired                       |             |        |               |                   |
| NEXT INSPECTION: Final and woodstove   |             |        |               |                   |
| RE-INSPECTION FEE  | DUE?        | NO YES |               | \$                |
| IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION |             |        |               |                   |
| QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL                  |             |        |               |                   |

**INSPECTION REQUEST LINE: 509-962-7694** 

ADDRESS:\_

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506

iessica.contratto @co.kittitas.wa.us