



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-15-00907

OWNER'S NAME: HANSEN

DATE: 10/19/2016

TYPE: Mechanical and plumbir

TIME STARTED: 12:48 PM

INSPECTOR: Jeremy Haberman

MAP NUMBER: 17-18-08059-0001

1. Retrofit HDU's Not Installed Properly. Connection to (2) Full Height Studs Required.
2. NOTE: Fresh Air Intake To Furnce Not Connected at this time.
3. NOTE: Range Vent Not Connected at this Time.
4. Protect Gas Tite Piping at Entry to Appliance.
5. Gas Line OK. 15#/15min. OK.
6. Supply/Exhaust Venting OK.
7. Plumbing Rough In OK. Supply at 50#/15min. OK. DWV on Stack.

INSTRUCTIONS: OK to Call for Framing

NEXT INSPECTION: Framing

RE-INSPECTION FEE DUE?



NO



YES

\$ _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL
ADDRESS: jeremy.haberman @co.kittitas.wa.us

INSPECTION REQUEST LINE: 509-962-7694

<http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx>

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506