INSPECTION REPORT

IIIOI ECITOR REI ORI			
PERMIT NUMBER:	BP-15-00921	OWNER'S NAME:	WT DEVELOPMENT
DATE:	3/24/2016	TYPE:	Mechanical and plumbir
TIME STARTED:	12:53 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	18-19-31077-0002		
 Framing completed also DWV not on test H20 at 30#, 50# minimum required Gas not on test Fireplace rough in ok Mechanical ok Vented windows installed Install vapor barrier behind guest shower Footings and posts at porch not complete Portal frame sheathing corrected on exterior. Header issue still outstanding Awaiting letter from engineer 			
INSTRUCTIONS: ok to insulate, see corrections then			
NEXT INSPECTION: insulation			
RE-INSPECTION FEE	DUE? V NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			
ADDRESS: <u>iessica.contratto</u> @co.kittitas.wa.us			

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506