## **INSPECTION REPORT**

INSPECTION REPORT			
PERMIT NUMBER:	BP-15-00928	OWNER'S NAME:	SMITH
DATE:	1/25/2017	TYPE:	Shearwalls
TIME STARTED:	12:11 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	17-18-22010-0026		
<ol> <li>Exterior nailing ok</li> <li>Clips at walls ok</li> <li>Complete install off 2 CS straps around corners on bumpout in great room.</li> <li>Connect header to perpendicular top plate at abutting wall</li> </ol>			
INSTRUCTIONS: Complete above, ok to cover			
NEXT INSPECTION: Plumb/mech			
RE-INSPECTION FEE	DUE? V NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			
ADDRESS:iessica.contratto @co.kittitas.wa.us			

**INSPECTION REQUEST LINE: 509-962-7694** 

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506