



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

## INSPECTION REPORT

PERMIT NUMBER: BP-16-00232

OWNER'S NAME: BACK COUNTRY

DATE: 7/27/2016

TYPE: Mechanical

TIME STARTED: 12:06 PM

INSPECTOR: Jeremy Haberman

MAP NUMBER: 19-15-07061-0010

1. Shear Correction At Rear Door OK.
2. Gas Line at 15#/15min. OK.
3. Fireplace Rough In OK. If Rafters are Battled.
4. Mechanical Supply and Exhaust OK.
5. NOTE: Main Supply Air Duct Not Insulated at This Time. Verify at Fianl.

INSTRUCTIONS: L&I Inspection Delayed. OK to Call fro Framing Once Electrical Rough In Complete.

NEXT INSPECTION: Framing.

RE-INSPECTION FEE DUE?



NO



YES

\$ \_\_\_\_\_

**IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION**

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL  
ADDRESS: jeremy.haberman @co.kittitas.wa.us

**INSPECTION REQUEST LINE: 509-962-7694**

<http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx>

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506