INSPECTION REPORT

PERMIT NUMBER:	BP-16-00249	OWNER'S NAME:	COVEY
DATE:	4/26/2017	TYPE:	Framing
TIME STARTED:	11:12 AM	INSPECTOR:	Justin Bennett
MAP NUMBER:	19-15-08051-0004		
 Trusses D2D & D4D have been modified @ bearing ends for outlookers - provide manufacturer Ok Truss B2 does not have clips @ bearing on porch beam Provide 4x6 post @ master window per review notes (3) locations Provide framing @ both ends of window wall per dwg - (3) kings & (2) trimmers Verify LSTA straps @ ridge beam per dwg Provide H2.5 @ Rafters per dwg Provide positive connection @ post to beam connection for side porch Provide strap @ sunroom beam to top plate connection (2) locations Fireplace and B Vent not installed NOTE: S10 has a note referring to updated Roof Framing dwgs - not on site Attic Access needed in Utility Rm Hall 			
INSTRUCTIONS: Complete above NEXT INSPECTION: Re-Inspection			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
	QUESTIONS? PLEASE CONTACT THE I ADDRESS:	NSPECTOR AT THE FO iustin.bennett @	
	· -= - · · - · · - · · · · · · · · · · ·	<u> </u>	

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506