INSPECTION REPORT

PERMIT NUMBER:	BP-16-00463	OWNER'S NAME:	ROSE
DATE:	12/5/2016	TYPE:	Floor framing
TIME STARTED:	11:27 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	17-23-19010-0004		
•	contact with treated wood need t age and along side of concrete s framing ok	•	h flashing
	k to cover all but areas requiring o	correction. These v	will need to be inspected before
NEXT INSPECTION: Re-inspect			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
	QUESTIONS? PLEASE CONTACT THE I ADDRESS: je	NSPECTOR AT THE FO	
INSPECTION REQUEST LINE: 509-962-7694			
http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx			
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			