INSPECTION REPORT

IIIOI ECITOR REI ORI			
PERMIT NUMBER:	BP-16-00463	OWNER'S NAME:	ROSE
DATE:	1/5/2017	TYPE:	Shearwalls
TIME STARTED:	2:35 PM	INSPECTOR:	Jeremy Haberman
MAP NUMBER:	17-23-19010-0004		
 Window Added at Southwest Corner of Structure in Shearwall Not Per Plan. ALL OTHER SHEAR OK. NOTE: Insulation Placed in Exterior Wall Behind Safe Room Verified. 			
INSTRUCTIONS: OK to Cover Exterior			
NEXT INSPECTION:	Plumb/Mech		
RE-INSPECTION FEE DUE? VES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: <u>ieremv.haberman</u> @co.kittitas.wa.us			
ADDINESS			

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506