INSPECTION REPORT

PERMIT NUMBER:	BP-16-00501	OWNER'S NAME:	COSTA
DATE:	1/5/2017	TYPE:	Re-inspection
TIME STARTED:	1:38 PM	INSPECTOR:	Jeremy Haberman
MAP NUMBER:	18-19-13000-0001		
 Outstanding Framing Corrections from 12/02/2016 Inspection Report Not Address ed. Re Fee Due Prior to Re Inspection. Porch soffits are enclosed - need to verify truss installation. Remove LP Fas cia Covering Porch Beams for Verification of Truss Clips and Beam Specifications Verify Range Vent Insulation at Insulation Inspection. Provide truss manufacturers approval to notch gable trusses for outlookers. P rovided Truss Sheets Do Not Specify. Need to verify detail 7/A4 @ soffits Header @ slider is 4x8 - 4x10 per dwgs. Provide Engineers Approval of Alterna te. Header not per plan for West window in Great Rm 			
INSTRUCTIONS: DO NOT INSULATE. Make Corrections Above. Call for ReInspection When Ready			
NEXT INSPECTION: Framing			
RE-INSPECTION FEE	DUE? NO VES		\$ 86.00
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: jeremy.haberman @co.kittitas.wa.us			
INSPECTION REQUEST LINE: 509-962-7694			

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506