## **INSPECTION REPORT**

INSI ECHON KEI OKI			
PERMIT NUMBER:	BP-16-00510	OWNER'S NAME:	PARKER
DATE:	6/28/2017	TYPE:	Framing
TIME STARTED:	11:33 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-14-27030-0009		
<ol> <li>Exterior shear ok except front wall</li> <li>Straps verified on front walls. Ok to cover</li> <li>Obtain engineered truss sheets from truss supplier</li> <li>Shim up sill plate to provide full stud bottom bearing at all walls</li> </ol>			
INSTRUCTIONS: Complete above			
NEXT INSPECTION:	Front shear/framing		
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			
ADDRESS: <u>iessica.contratto</u> @co.kittitas.wa.us			

**INSPECTION REQUEST LINE: 509-962-7694** 

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506