



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-16-00587

OWNER'S NAME: MAGRUDER

DATE: 5/17/2017

TYPE: Framing

TIME STARTED: 9:37 AM

INSPECTOR: Jeremy Haberman

MAP NUMBER: 20-14-36053-0001

1. Gas Line OK. 45#/15min. OK.
2. Mechanical Exhaust OK.
3. Range Exhaust Not Complete.
4. NOTE: Exterior/Interior Shear Inspection to be Completed by Engineer of Record Per Engineer.
5. NOTE: Fireplace Rough In to Be Seen Prior to Cover.
6. Framing OK.

INSTRUCTIONS: OK to Insulate.

NEXT INSPECTION:

RE-INSPECTION FEE DUE?



NO



YES

\$ _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL
ADDRESS: jeremy.haberman @co.kittitas.wa.us

INSPECTION REQUEST LINE: 509-962-7694

<http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx>

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506