INSPECTION REPORT

PERMIT NUMBER:	BP-16-00597		OWNER'S NAME:	LEENSVAART	
DATE:	2/17/2017		TYPE:	Multiple (see notes)	
TIME STARTED:	11:56 AM		INSPECTOR:	Jessica Contratto	
MAP NUMBER:	17-19-28000-0046				
1. Framing ok 2. Bath fan need 3. DWV at 7#-ok 4. H20 at 75#-ok					
INSTRUCTIONS: O	k to insulate. Duct fan				
NEXT INSPECTION:	Insulation				
RE-INSPECTION FEE	Ľ	YES		\$	
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
	QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:				
		.			

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506