



KITITITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-16-00621

OWNER'S NAME: TROUT

DATE: 4/5/2017

TYPE: Exterior shear

TIME STARTED: 12:52 PM

INSPECTOR: Justin Bennett

MAP NUMBER: 20-15-29051-0084

1. Tighten up nailing in (2) locations - in progress
2. Interior Shear not complete
3. HD's installation not complete - verify @ framing
4. Engineer letter for MST vs Balloon in process - not on site
5. Straps in doorways (2) locations - clouded on dwgs
6. Exterior MST straps Ok

INSTRUCTIONS: Complete above/Once complete Ok to cover/Interior shear,HD's and Engineer letter to be seen by Framing

NEXT INSPECTION: Plumb/Mech

RE-INSPECTION FEE DUE? NO YES \$ _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL
ADDRESS: _____ [justin.bennett @co.kittitas.wa.us](mailto:justin.bennett@co.kittitas.wa.us)

INSPECTION REQUEST LINE: 509-962-7694

<http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx>

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506