INSPECTION REPORT

PERMIT NUMBER:	BP-16-00695	OWNER'S NAME:	RICHTER
DATE:	6/9/2017	TYPE:	Framing
TIME STARTED:	1:45 PM	INSPECTOR:	Justin Bennett
MAP NUMBER:	21-16-31020-0007		
 All headers require (1) Jack & (2) Kings typical unless noted otherwise Verify MST & CS strapping @ top of beam to top plate connection - Multiple lo cations Front porch soffit enclosed - need to verify ledger attachment and framing Rear Porch not complete Roof sheathing edge blocking not complete - clouded on page 5 Ledger for kitchen/utility ceiling attached with nails - provide engineer att achment detail Range Vent not installed in kitchen EF in bathroom & utility room not ducted/terminated Gas @ 5# - needs to be 15#/15 mins 			
INSTRUCTIONS: Complete above NEXT INSPECTION: Re-Inspection RE-INSPECTION FEE DUE? YES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			
	ADDRESS:	iustin.bennett @	

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506