## **INSPECTION REPORT**

PERMIT NUMBER:	BP-17-00065	OWNER'S NAME:	HASH
DATE:	5/26/2017	TYPE:	Mechanical and plumbir
TIME STARTED:	1:34 PM	INSPECTOR:	Justin Bennett
MAP NUMBER:	17-18-12040-0001		
1. DWV @ 5#/15 mins - Ok 2. Supply @ 38# - Needs to be 50# 3. HVAC SA/RA Ok 4. HVAC OA confirmed 5. EF not ducted 6. Trusses Ok 7. Framing Ok			
INSTRUCTIONS: Pressurize supply to 50#/Verify EF Ducting			
NEXT INSPECTION: Insulation			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			
ADDRESS: iustin hennett @co.kittitas.wa.us			

**INSPECTION REQUEST LINE: 509-962-7694** 

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506