INSPECTION REPORT

PERMIT NUMBER:	FO-15-00036	OWNER'S NAME:	SCARSELLA
DATE:	9/3/2015	TYPE:	Footings
TIME STARTED:	11:14 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-14-24050-0214		
1. setbacks ok			
2. footings ok			
3. some interior footings and pads will be poured after backfill work. Rebar is stubbed fr			
om existing formwork to prevent cold joints			
4. garage will be excavated and poured later			
INSTRUCTIONS: ok to pour			
NEXT INSPECTION: walls/interior footings			
RE-INSPECTION FEE DUE? VES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
<u>iessica.contratto</u> @co.kittitas.wa.us			
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 ◆ 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 ◆ Main Office Line: 509-962-7506 			