

Attachment to sheet 2 of the drawings

***NOTE**

No demonstrative signs of an OHWM were found at the bankfill level of the soil between the river and the cabin/deck structures. If the signs were ever there, they were evidently destroyed by the ongoing riverbank erosion problems at the project site.