INSPECTION REPORT

| PERMIT NUMBER: | BP-13-00337 | OWNER'S NAME: | KLIPPA HUS LLC |
|--|------------------|---------------|-------------------|
| DATE: | 8/8/2014 | TYPE: | Rough-in plumbing |
| TIME STARTED: | | INSPECTOR: | Jessica Contratto |
| MAP NUMBER: | 20-15-29050-0135 | | |
| 1. H20 is | live- ok | | |
| 2. DWV o | on stack | | |
| 3. DWV in upstairs to right is not on stack test | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| INSTRUCTIONS: put DWV on test in upstairs bath | | | |
| | | | |
| NEXT INSPECTION: re-inspect or see at frame/mech | | | |
| RE-INSPECTION FEE I | DUE? NO YES | | \$ |
| IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION | | | |
| QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: | | | |
| jessica.contratto @co.kittitas.wa.us | | | |
| • INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 • | | | |