



KITITITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-14-00129 OWNER'S NAME: CALHOUN
 DATE: 9/16/2014 TYPE: Exterior shear
 TIME STARTED: 11:10 AM INSPECTOR: Jessica Contratto
 MAP NUMBER: 17-17-01052-0001

1. BWP and portal framed areas at garage doors not nailed per plan. See handout in plan re view packet for info
2. 1000lb straps to header required opposite sheathing on portal framing. See by framing inspection. See handout
3. windows added in braced wall panels. Come in to office for BWP revision
4. Field nailing not 12" O.C. on most panels.
5. Panel at left corner of house not edge nailed.
6. Tighten upedge nailing on panels where needed to 6"

INSTRUCTIONS: complete above, do not cover. Call for re-inspeccion

NEXT INSPECTION: re-inspection

RE-INSPECTION FEE DUE? NO YES \$ _____
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

_____ [jessica.contrato @co.kittitas.wa.us](mailto:jessica.contrato@co.kittitas.wa.us)

• **INSPECTION REQUEST LINE:** www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 •
 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506