INSPECTION REPORT

BP-14-00751

PERMIT NUMBER:

OWNER'S NAME: NEW SUNCADIA LLC

DATE:		7/29/2015	TYPE:	Framing	
TIME STARTED:		11:00 AM	INSPECTOR:	Jeremy Haberman	
MAP NUMBER:		20-15-29051-0018			
	1. Inspection Report from 7/27/2015 Missing from T Drive. Plumbing OK per that Report.				
	2. Gas Not at Required PSI.				
	3. Garage Mechanical Alcove Floor Not Fire Protected.				
	4. Duct Chase Drafttop Not Complete in Duct Chase Near Garage Attic.				
	5. Trusses OK.				
	6. Attic Access Not Provided to Attic Space above Uptairs Bedroom #4/Bath.				
	7. Heel of Lower Stair Jacks Not Fully Bearing.				
	8. Additional Posting Required at Double LVL Overhead at Stairwell.				
	9. Additional Posting at Girder in "Jr. Suite" Required.				
	10. Posts at Entry Non-Pressure Treated in Contact with Ground.				
	11. Repair Sherwall in Bathroom Upstairs.				
INSTRUCTIONS: Make Corrections Above. OK to Insulate.					
NEXT INSPECTION: Insulation.					
RE-INSPECTION FEE DUE? VES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
jeremy.haberman @co.kittitas.wa.us					
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506					