## **INSPECTION REPORT**

BP-14-00786

**PERMIT NUMBER:** 

OWNER'S NAME: FORTUNE CREEK

DATE:		6/29/2015	TYPE:	Exterior shear
TIME STARTED:		9:48 AM	INSPECTOR:	Jeremy Haberman
MAP NUMBER:		19-15-07061-0015		
1	1. Exterior Shear OK.			
2	2. Interior Shear Not Complete at Basement Bedroom/Bath Wall. HDU Next to Tub Missing.			
INSTRUCTIONS: OK to Cover Exterior. Call For Interior Shear Once Complete.				
NEXT INSPECTION: Interior Shear/Plumb/Mech.				
RE-INSPI	ECTION FEE I	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION				
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:				
jeremy.haberman @co.kittitas.wa.us				
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 •				
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506				