INSPECTION REPORT

PERMIT NUMBER: BP-15-00204 OWNER'S NAME: MATLOCK

DATE:	8/5/2015	TYPE:	Floor framing
TIME STARTED:	2:26 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	19-14-02054-0003		
1. floor framing ok			
2. Radon loop and sealed membrane installed in crawl			
INSTRUCTIONS: Ok	to cover floor		
MSTROCTIONS. OR to cover floor			
NEXT INSPECTION: shearwalls			
RE-INSPECTION FEE DUE? VES \$ IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
iessica.contratto @co.kittitas.wa.us			
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			
TIT IN Hady Street, Suite 2, Enchastary, With Source and Street, 505 502 7500			