INSPECTION REPORT

PERMIT NUMBER:		BP-15-00204	OWNER'S NAME:	MATLOCK	
DATE:		10/6/2015	TYPE:	Rough-in mechanical	
TIME STARTED:		10:21 AM	INSPECTOR:	Jessica Contratto	
MAP NUMBER:		19-14-02054-0003			
	1. DWV on s	stack-ok			
	2. H2O at 70#-ok				
	3. Hydronics at 100#-ok				
	4. Exhaust duct ok				
	5. See range and dryer vent at final				
	6. Fresh air intakes will be installed in rooms by final				
	7. Complete radon mitigation inspection in crawl by final				
	8. Fireplace not installed. See at final. Will be visible				
	9. Gas piping in garage for generator not yet installed				
INSTRUCTIONS: Exterior walls and roof are SIPS panels. Interior walls will be insulated for sound. Ok to					
cover once framing inspection is passed					
NEXT INSPECTION: Framing					
RE-INSPECTION FEE DUE? VES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	iessica.contratto @co.kittitas.wa.us				
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 					