## **INSPECTION REPORT**

PERMIT NUMBER: BP-15-00207 OWNER'S NAME: IVERSON

DATE:	7/8/2015	TYPE:	Floor framing
TIME STARTED:	12:07 PM	INSPECTOR:	Justin Bennett
MAP NUMBER:	20-14-19053-0002		
Complete anchor bolt installation on south side			
2. Crawl access Ok			
3. HD's Ok			
INSTRUCTIONS: Complete correction above/Once complete ok to cover			
NEXT INSPECTION: Exterior Shear			
RE-INSPECTION FEE DUE? VES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
iustin_bennett @co.kittitas.wa.us			
• INSPECTION REQUEST LINE: <a href="www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			