



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-15-00215

OWNER'S NAME: WEST

DATE: 1/13/2016

TYPE: Framing

TIME STARTED: 11:19 AM

INSPECTOR: Jeremy Haberman

MAP NUMBER: 20-14-24050-0517

	1. NOT READY FOR FRAMING. MECHANICAL INSPECTION NOT COMPLETED.
	2. Gas Line Not at Required PSI. 15 PSI Required.
	3. Fireplace Rough In Draftstop Not Complete. Fireblocking Required in Stud Bays Behind OS
	B.
	4. Exhaust Supply Duct Work OK.
	5. P1-4 2x8 Interior Shear Wall Missing at Stairs
	6. Hole in P1-6 Shearwall at Kitchen Not Acceptable.
	7. Outstanding Exterior Shear Corrections OK.

INSTRUCTIONS: Make Corrections Above. Call for Framing.

NEXT INSPECTION: Framing.

RE-INSPECTION FEE DUE?



NO



YES

\$ _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

_____ jeremv.haberman@co.kittitas.wa.us

• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 •

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506