INSPECTION REPORT

PERMIT NUMBER:	BP-15-00215	OWNER'S NAME:	WEST
DATE:	2/5/2016	TYPE:	Insulation
TIME STARTED:	11:02 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-14-24050-0517		
 Panel edge blocking on right side of master bed wall not replaced Draftstop needed at ceiling penetration on fireplace Also provide insulation shield at chimney at ceiling Wall cavity where blocking missing is not foam flashed. Provide R-21 insulation in this area after completing blocking Wall and vault insulation ok 			
INSTRUCTIONS: complete above, inspect corrections or have photos for verification before proceeding			
NEXT INSPECTION: re-inspect or pics remaining corrections			
RE-INSPECTION FEE	DUE? V NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: <u>iessica.contratto</u> @co.kittitas.wa.us			
INSPECTION REQUEST LINE: 509-962-7694 http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx			

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506