INSPECTION REPORT

| PERMIT NUMBER: | BP-15-00243 | OWNER'S NAME: | CHERNYAK |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------|---------------|------------------------|
| DATE: | 6/23/2016 | TYPE: | Mechanical and plumbir |
| TIME STARTED: | 12:52 PM | INSPECTOR: | Justin Bennett |
| MAP NUMBER: | 22-11-09054-0033 | | |
| Plumbing rough in Ok Supply live - Ok DWV @ 15#/15 mins - Ok Mechanical condensing exhaust hung from waste line in garage HVAC supply compromised stud @ east side of garage wall Mechanical exhaust Ok | | | |
| INSTRUCTIONS: | | | |
| NEXT INSPECTION: Framing | | | |
| RE-INSPECTION FEE DUE? NO YES \$ IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION | | | |
| QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: <u>iustin.bennett</u> @co.kittitas.wa.us | | | |
| INSPECTION REQUEST LINE: 509-962-7694 | | | |

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506