



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-15-00244

OWNER'S NAME: BUTLER

DATE: 7/15/2015

TYPE: Footings

TIME STARTED: 9:43 AM

INSPECTOR: Jeremy Haberman

MAP NUMBER: 20-15-36058-0003

	1. ReBar Installation In Footing Portion Not Complete.
	2. Wire Mesh Not Complete in Slab Portion.
	3. Setbacks OK.
	4. If Fiber Mesh is Used Instead of Wire Mesh Engineers Letter Will be Required.

INSTRUCTIONS: Make Corrections Above. DO NOT POUR.

NEXT INSPECTION: Re Inspect

RE-INSPECTION FEE DUE? NO YES \$ _____
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

_____ jeremy.haberman@co.kittitas.wa.us

● **INSPECTION REQUEST LINE:** www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 ●
 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 ● Main Office Line: 509-962-7506