## **INSPECTION REPORT**

BP-15-00245

**PERMIT NUMBER:** 

OWNER'S NAME: BUTLER

DATE:		7/15/2015	TYPE:	Footings	
TIME STARTED:		9:46 AM	INSPECTOR:	Jeremy Haberman	
MAP NUMBER:		20-15-36058-0003			
	1. Rebar Not Complete in Footing Portion.				
	2. Wire MEsh Not Complete in Slab Portion.				
	3. Setbaccks OK.				
	4. If Fiber Mesh is Used Instead of Wire MEsh Engineers Letter will be Required.				
INSTRUCTIONS: MakeCorrections Above. DO NOT POUR					
NEXT INSPECTION: Re Inspect					
RE-INSPECTION FEE DUE? VES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	jeremy.haberman @co.kittitas.wa.us				
■ INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 ■  411 N. Ruby Street, Suite 2. Ellensburg, WA 98926 ■ Main Office Line: 509-962-7506					