## **INSPECTION REPORT**

OWNER'S NAME: GRISWOLD

PERMIT NUMBER: BP-15-00276

DATE:		7/16/2015	TYPE:	Framing
TIME STARTED:		3:22 PM	INSPECTOR:	Justin Bennett
MAP NUM	1BER:	19-16-06050-0007		
1.	1. Floor framing Ok			
2.	. Crawl access Ok			
3.	3. Ok to cover			
INSTRUCTIONS: Ok to cover				
NEXT INSPECTION: Exterior Shear				
RE-INSPECTION FEE DUE? VES \$				
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION				
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:				
iustin_bennett @co.kittitas.wa.us				
<ul> <li>INSPECTION REQUEST LINE: <a href="www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694 ◆</li> <li>411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 ◆ Main Office Line: 509-962-7506</li> </ul>				
, , , , , , , , , , , , , , , , , , , ,				